

PROCESSING CONDITIONS
CRYSTAL WST / CRYSTAL SHEA / CRYSTAL GOATS MILK

1. Remove the soap from the container.
 2. **If using an 11.5kg block of soap either use the whole block or, if less is required, cut a vertical section from top to bottom of the block. i.e. Do not take from the top or bottom only.**
 3. Transfer to a suitable vessel with a heating facility and agitator.
 4. Gently heat the product to the 70°C. **Do not exceed this temperature.** When melted, start the agitator.
 5. Charge perfume, dye and additives.
 6. When fully mixed, cool to 65°C with slow stirring (to avoid air entrapment). Turn off the agitator.
 7. Discharge through a fine mesh filter into suitable moulds.
 8. Allow product to solidify.
 9. Do not pack or hand stamp for 24 hours.
-