

THE SOAP KITCHEN. PERCENTAGE-BANDINGS FOR KAYS SOAPS

Claranol Transparent Soap Base Percentage Bandings

Aqua	25-50%
Propylene Glycol	10-25%
Sodium Stearate	10-25%
Sodium Laureth Sulfate	10-25%
Glycerine	10-25%
Sucrose	5-10%
Sodium Cocoate	5-10%
Sodium Xylene Sulphonate	5-10%
Sodium Lauryl Sulfate	1-5%
Stearic Acid	1-5%
Tetrasodium EDTA	<0.1%
Tetrasodium Etidronate	<0.1%

Claranol Opaque Soap Base percentage Bandings

Aqua	25 -50%
Propylene Glycol	10 -25%
Sodium Stearate	10 -25%
Sodium Laureth Sulfate	10 -25%
Glycerine	10 -25%
sucrose	5 -10%
Sodium Cocoate	5 -10%
Sodium Xylene Sulphonate	5 -10%
Sodium Lauryl Sulfate	1 - 5%
Titanium Dioxide	0.5 -1%
Stearic Acid	0.5 -1%
Tetrasodium EDTA	<0.1%
Tetrasodium Etidronate	<0.1%

Claranol Transparent SLS-Free Soap Base Percentage Bandings

Aqua	25-50%
Propylene Glycol	10-25%
Sodium Stearate	10-25%
Sodium Laureth Sulfate	10-25%
Glycerine	10-25%
Sucrose	5-10%
Sodium Cocoate	5-10%
Sodium Xylene Sulphonate	5-10%
Stearic Acid	1-5%
Tetrasodium EDTA	<0.1%
Tetrasodium Etidronate	<0.1%

Claranol Opaque SLS-Free Soap Base Percentage Bandings

Aqua	25 -50%
Propylene Glycol	10 -25%
Sodium Stearate	10 -25%
Sodium Laureth Sulfate	10 -25%
Glycerine	10 -25%
sucrose	5 -10%
Sodium Cocoate	5 -10%
Sodium Xylene Sulphonate	5 -10%
Titanium Dioxide	0.5 -1%
Stearic Acid	0.5 -1%
Tetrasodium EDTA	<0.1%
Tetrasodium Etidronate	<0.1%

Kays Organic Liquid Soap Base Percentage Bandings

Aqua	50 -100%
Potassium Oleate	10 -25%
Potassium Cocoate	10 -25%
Glycerine	1 - 5%
Potassium Chloride	0.5 -1%
Patassium Citrate	0.1 - 0.5%